

T-1100 WEATHER COVER INSTRUCTIONS:




Step 1: Remove hanger bolts and bracket. As well as carrying handle and bolts as shown.



weather cover

Step 2: Slide cover over machine with square nozzle hole toward front. Line up with corner of machine, punch hanger bolt and handle holes.



Step 3: Fasten all bolts back securely as shown.